




SPRINTER VAN - DODGE 03-06
FREIGHTLINER 96-06



REPLACEMENT SHEETMETAL

Index#	Description	Year	Mill Part#
N.I.	Front fender	96-06	285-03-20
N.I.	Front wheel lower rear section, between wheel & door 31"H and extends 12" toward rocker	96-06	285-03-21
N.I.	Doorskin, front door, lower outer, 26"H	96-06	285-03-31
31A	Doorskin, front door, lower outer, 12"H	96-06	285-03-31A
33	Doorskin, sliding side door, lower outer, universal L=R 47"L x 15"H	96-06	285-03-33
36	Doorskin, rear cargo door, lower outer, 31"L x 19"H	96-06	285-03-36
N.I.	Rocker panel, front door, 34"L	96-06	285-03-40
N.I.	Rocker panel, side sliding door, 47"L x 7"H	96-06	285-03-43
51	Rear wheel arch area, 42"L x 28"H	96-06	285-03-51
53	Lower LH side repair panel, 47"L x 19"H	96-06	285-03-53
55	Rear quarter, lower front section, LWB, 50"L x 17"H	96-06	285-03-55
57	Rear quarter, lower rear section, LWB, 42"L x 16"H	96-06	285-03-57
64	Rear panel below rear doors, 56"W x 9-3/4"H	96-06	285-03-64

SUZUKI SAMURAI 86-95



40

REPLACEMENT SHEETMETAL

Index#	Description	Year	Mill Part#
40	Rocker panel, 2DR	86-95	368-86-40

SUZUKI SIDEKICK/GEO TRACKER 89-98



40

REPLACEMENT SHEETMETAL

Index#	Description	Year	Mill Part#
N.I.	Front inner fender	89-98	369-89-25
N.I.	Doorskin lower, 2DR	89-98	369-89-31
N.I.	Inner door bottom, 2DR, universal	89-98	369-89-32
40	Rocker panel, 2DR	89-98	369-89-40
N.I.	Rocker panel extension, 4DR, (attach to 2DR rocker)	89-98	369-89-41

TOYOTA PICK-UP 79-88

REPLACEMENT BODY PANELS

Index#	Description	Year	Mill Part#
N.I.	Fender, 2WD	79-83	*377-79-20
N.I.	Fender, 2WD	84-88	*377-84-22
N.I.	Fender, 4WD	84-88	*384-84-20
N.I.	Rocker, 2 & 4 WD	79-83	377-79-40
N.I.	Upper rear wheel arch, 11"x 36", 2 & 4 WD, universal	84-88	377-84-52

Specify LH (Drivers Side) or RH (Passenger Side) when ordering

All manufacturers' names, numbers, and descriptions are used for reference purposes only. It is not implied that any part listed is the product of the original manufacturers or approved by any of these manufacturers.



Bold Type - New Item • * Too large for UPS • N.I. Not Illustrated
800-888-5072 • Toll Free Fax 888-781-2700
Visit our web site: www.rustrepair.com